

Event Date	Operating Airline	Flight Number	Departure Airport	Arrival Airport	Aircraft Registration Number	Aircraft Type	Event Summary	Investigating Country (Investigating Authority)	Official Investigation Report by	Status of Company-Internal Investigation Committee
2024/2/1	ANA	NH849	HND	BKK	JA899A	B787-9	The aircraft encountered turbulence while cruising an hour after taking off from Haneda Airport. At that time, one CA who was providing customer service twisted his leg. Another CA was hit by a service cart and sustained abrasions on his leg. After returning to Japan, CA, who had twisted his leg, visited a hospital and was diagnosed with a fracture of the lateral malleolus of his right ankle.	Japan JTSB	<a href="#">investigating</a>	